

I.C.R. W.U.A. Monthly Operator Notes
October 25, 2016

Molly Way was flushed twice and the fire pumps exercised.

The easement road was checked twice to insure no leaks or issues with our line

Tank painters completed work on Cooper Morgan tank

Inline filter will be installed on the Molly Way boost station

Called about a leak on Turning Mountain (ICR) found to be on owners side of the meter

2 meters install 2 (TRR) (1) bad meter replaced (TRR)

Yearly Hydrant leak detection has started

Yearly valve exercise program is ongoing

Weed abatement is on-going

Meter reads went well this month

Monthly samples were collected and delivered to the lab. (No issues)

All equipment is working properly at this time with the exception of the Molly Way
program issue